


WIRING DIAGRAM FOR PMV5340_1V0(FOUR SELECTION)



PULSARS,
 #14, SIDCO Industrial Estate,
 Thirumudivakkam,
 Chennai-600 044, India
 Ph-044 2478 3099




Title WIRING DIAGRAM FOR PMV5340_1V0		
Size A4	Document Number <Doc>	Rev <RevCode>
Date: Thursday, May 31, 2007	Sheet 1	of 1


BOTTOM VIEW

PMV5340_1V0

**WHILE IN
SETTING
MODE**



SMPS



NOTE :

FOR FILLING :

PRESS HOT WATER KEY CONTINUOUSLY FOR 3 SECONDS.

FOR COUNT DISPLAY :

PRESS HOT WATER KEY CONTINUOUSLY FOR 2 SECONDS & RELEASE THE KEY & AGAIN PRESS THE SAME KEY.

FOR FLUSHING :

PRESS HOT WATER KEY CONTINUOUSLY FOR 2 SECONDS & RELEASE THE KEY & PRESS ANYOTHER KEY.

FOR HALF CUP :

PRESS HOT WATER KEY CONTINUOUSLY FOR 1 SECOND & RELEASE THE KEY & PRESS ANYOTHER KEY.

PULSARS,
#14,SIDCO Industrial Estate,
Thirumudivakkam,
Chennai-600 044,India
Ph-044 2478 3099



Title		
WIRING DIAGRAM FOR PMV5340_1V0		
Size	Document Number	Rev
A4	<Doc>	<RevCode>
Date:	Thursday, May 31, 2007	Sheet 1 of 1